

# Village of Chippewa Lake

## Zoning Report - July

- 292 Briarwood** - Driveway needs coated with stone, truck parked in yard, premises conditions.  
-Progress is being made.  
-Corrected.
- 171 Brookshore** - Fence needs structural maintenance, overgrowth, garage needs painted.  
-In Progress. The fence has been straightened and work on the garage (replacement of panels)
- 273 Rustic Rook** - Letter for correction mailed to owner.  
-No response/has not been corrected. Proceed filing charges with court.  
-Corrected.
- 306 Briarwood** - Letter for correction posted on the premises. Exterior walls need scraped and painted.
- 236 Circle Crest** - Letter for correction hand delivered to address. Exterior walls need scraped and painted. Owner plans to vinyl side the structures. Has purchased the siding already looking for installer. - Found installer. Scheduled for July.
- 239 Circle Crest** - Letter for correction posted and mailed to the owner. Exterior walls need scraped and painted.
- 587 Lake** - Letter mailed to owner for Property Maintenance issues. - Owner will be working on it.
- 584 Lake** - Letter mailed to owner for Property Maintenance issues. - Owner removing barn.
- 583 Lake** - Letter mailed to owner for Property Maintenance issues. - Renter will be working on it.
- 566 Chippewa Rd.** - Warning notice issued for roof replacement and brush pile.  
-Corrected.

## Permits

**19-014 - 204 Park Lake**  
**PN# - 048-28A-03-141**  
**Permit - New Home**

**19-015 - 202 Richard Drive**  
**PN# - 048-28A-04-227**  
**Permit - Garage**

**19-016 - 456 Northvale Drive**  
**PN# - 048-28A-03-231 & (052)**  
**Permit - Shed**

**19-017 - 126 Bass Bay**  
**PN# - 048-28A-03-142**  
**Permit - Driveway/Patios**

**19-018 - 163 Rockridge**  
**PN# - 048-28A-04-201 (202)**  
**Permit - Covered Deck**