

# Village of Chippewa Lake

## Zoning Report - December

**171 Brookshore** - Garage needs to be painted.

-Work will continue in the spring.

**587 Lake** - Letter mailed to owner for Property Maintenance issues.

-Forwarded the case to Allan.

**584 Lake** - Letter mailed to owner for Property Maintenance issues.

- Owner has scheduled to have the amish remove the barn as soon as they can.

**258 Rustic Rook** - Warning Notice posted and sent digitally for Property Maintenance issues.

- Work has begun with replacing the windows and the siding installation is next.

**286 Briarwood** - Warning Notice posted for scraping and painting the garage.

- The garage has been scraped and prepared for painting. They are waiting for the weather.

May not be able to continue until spring.

**173 Rockridge** - Warning Notice posted for high grass and a brush pile in the backyard.

-The grass has been cut.

**374 Craggy Creek** - Warning Notice for parking in the front yard.

**127 Rockridge** - Warning Notice posted on the property for Inoperable/Unlicensed vehicle on the side of the road.

### Permits Issued

<b>19-032</b>	<b>43 Bungalow Bay</b>
<b>PN#</b>	<b>048-28A-05-083</b>
<b>Permit</b>	<b>Addition with attached garage</b>

**Variance Hearing for 64 Bungalow Bay - Encroachment into setback requirements.**